

Compact Hygro-thermometer

FEATURES

- Dual Display for Humidity and Temperature
- Maximum & Minimum Reading Memory
- Ice Point Alert
- Outdoor Temperature Display
- °C / °F Exchange
- Foldaway Stand
- Mounting keyhole
- Velcro Magic Tape Fixing

OPTIONS

- ① Hygro-thermometer
- ② Hygro-thermometer with outdoor sensor

SPECIFICATION

Measuring range	20 ~ 99% 0 ~ 50°C / 32~122°F (indoor), -50 ~ 70°C / -58 ~ 158 °F (outdoor)
Display accuracy	±3%, ±1°C / ±2°F
Display resolution	1%, 0.1°
Display update	10 seconds
Battery	1.5 volt, size AAA or equivalent x1 piece
Ice point alert	Outdoor reading ≤ 0 °C / 32 °F (option ② only)
Display size	36(W) x 16(H) mm
Product size	65(W) x 97(H) x 20(D) mm
Accessories	1) Outdoor sensor with 3 meters sensor cord x1 piece (option ② only) 2) Sensor holder x1 piece (option ② only) 3) 1.5 volt, size AAA battery x1 piece

INSTALLATION

1. Use sensor holder to fix outdoor sensor at desired outdoor space (option ② only).
2. Plug outdoor sensor into unit (option ② only).
3. Install battery with correct polarity positioning.
4. The unit will perform a self-test and display readings normally after 5 seconds.
5. Place unit at the place away from direct sunlight, rain or extreme heat.
6. Peel off display protective sheet.

OPERATION

1. Maximum/minimum reading memory
 - a. Press [Max/Min] button to display maximum measured value, press the button once more to display minimum measured value, press the button again to return to normal display.
 - b. Press and hold [Max/Min] button until two bars "---" are displayed then release to reset memory.
2. Outdoor temperature display (option ② only)
 - a. Press [OUT DOOR] button to display outdoor temperature.
 - b. Press the button again to display normally.
3. Ice point alert (option ② only)
Press [ALERT] to switch on ice point alert function and alarm will sound when outdoor temperature is ≤ 0 °C.
4. °C / °F exchange
Press [°C/°F] button to change temperature unit.
5. Power on/off
Press [ON/OFF] button to switch off/on unit.